

Honda Model Number Identification

| | Manufacturer | Horse-power | Model Year | Shaft Length | Steering System | Market |
|------------|--------------|-------------|---|--------------------|---|--------------|
| BF2 | BF = Honda | EX: 2 | DX = 1999 DY = 2000 D1 = 2001 D2 = 2002 D3 = 2003 D4 = 2004 D5 = 2005 D6 = 2006 DK0 = 2007-up | S = 15" L = 20" | H = Throttle Grip C = Centrifugal Clutch | A = American |

EXAMPLE: BF2D1SCHA = Honda, 2 HP, 2001 Model, 15", Centrifugal Clutch w/Throttle Grip, American

| | Manufacturer | Special Features | Horse-power | Model Year | Shaft Length | Steering System | Starter | Market |
|-----------------|--------------|--|----------------|---|--------------------------------|---|---|--------------|
| BF5-BF20 | BF = Honda | P = High Thrust Propeller = Standard Propeller | EX: 5 20 | D1 = 2001 D2 = 2002 D3 = 2003 D4 = 2004 D5 = 2005 D6 = 2006 DK0 = 2007-up | S = 15" L = 20" XL = 25" | H = Throttle Grip C = Centrifugal Clutch | S = Electric T = Manual Electric w/ Power Tilt | A = American |


EXAMPLE: BFP5D1LHSA = Honda, High Thrust Prop., 5 HP, 2001 Model, 20", Throttle Grip, Elec. Start, American

| | Manufacturer | Horse-power | Model Year | Shaft Length | Steering System | Tilt & Trim | Market |
|-------------------|--------------|-------------------------|--|---|---|--|--------------|
| BF25-BF225 | BF = Honda | EX: 25 115 225 | AX = 1999 AY = 2000 A1 = 2001 A2 = 2002 A3 = 2003 A4 = 2004 A5 = 2005 A6 = 2006 K0 = 2007-up | S = 15" L = 20" X = 25" XX = 30" | R = Remote Control H = Tiller Handle | T = Tilt & Trim = Manual Tilt J = Jet Drive | A = American |

EXAMPLE: BF25A1LRTA = Honda, 25 HP, 2001 Model, 20", Remote Control, Tilt & Trim, American

NOTE: After the 2006 model year Honda Marine dropped specific year designations.

| | | |
|---|--|--|
|  |  |  |
| <p>18-7494 COIL Replaces: 30520-PNA-007 Fits: 130/ 135/ 150/ 105 jet/ & 150 HP VTEC 1998-2007</p> | <p>18-23251 IGNITION COIL Replaces: 30520-PWC-003 Fits: BF75(2007 & Up), BF90(2007 & Up)</p> | <p>18-5224 18-5224-9^① SPARK PLUG WIRE TERMINAL</p> |

| | | | |
|---|---|--|---|
|  |  |  |  |
| <p>18-5225 SPARK PLUG WIRE KIT Kit includes 25 ft. Roll of 7 MM Hypalon Ignition Wire With a Metallic Core and a Large Assortment of Three Different End Fittings to Fit Outboard Motors.</p> | <p>18-5226 IGNITION WIRE Metallic Core 100' Spool 7mm Hypalon</p> | <p>18-5750 18-5750-9^① UNIVERSAL SPARK PLUG BOOTS Supplied complete with Terminal Connector</p> | <p>18-5752 UNIVERSAL SPARK PLUG BOOT (8mm)</p> |

| | | |
|--|---|---|
|  |  |  |
| <p>18-6475 ALTERNATOR Replaces: 31630-ZW5-003 Fits: BF115 (1999 & Up), BF130 (1999-2004)</p> | <p>18-6476 ALTERNATOR Replaces: 31630-ZY6-003 Fits: BF135 & BF150 (2004 & Up)</p> | <p>18-6433 OUTBOARD STARTER Replaces: 31200-ZV5-013 Fits: 40 H.P. (1999-UP)</p> |

^① Priced per Package

| | | |
|---|---|--|
|  <p>18-6445 STARTER Replaces: Honda 31200-ZW9-802 Fits: 8 & 9.9HP (2001 & Up)</p> |  <p>18-6959 STARTER Replaces: 31200-ZY6-003, 31200-ZY9-003, 31200-ZY9A-0031 Fits: 75-150HP 2004-2010</p> |  <p>18-15061 OUTBOARD STARTER Replaces: 31200-ZW1-004 Fits: BF75-90(1997-06)</p> |
|  <p>18-6258 TILT/TRIM MOTOR Replaces: 36120-ZV5-821 Fits: BF35,BF40,BF45,BF50 (1992-2002)</p> |  <p>18-6742 TRIM MOTOR Replaces: 36120-ZY3-023 Fits: 200-225 HP (02-Up), 175 HP (07-Up)</p> |  <p>18-6743 TRIM MOTOR Replaces: 36120-ZY9-003 Fits: 75-90 HP (07-Up)</p> |
|  <p>18-6745 TRIM MOTOR Replaces: 36120-ZY6-013 Fits: 135-150 HP (04-Up), 115 HP (07-Up)</p> |  <p>18-6793 TRIM MOTOR Replaces: 36120-ZV5-822 Fits: 40,50 H.P. (2002-03)</p> |  <p>18-6823 WIRING HARNESS Replaces: Universal Converts 3-wire Tilt and Trim motors to 2-Wire design</p> |

FUEL WATER SEPARATORS



Sierra offers a complete line of 10 and 21 micron fuel water separating filters including drainable bowl filters to protect your carbureted and fuel injected engine.

Refer to pages 136-140 for a complete listing of OEM and universal applications.

Sierra fuel water separators remove over 99.8% of emulsified water from your gasoline. Sierra's 10 micron filters are over 90% efficient at removing particles as small as 10 micron. All filters flow @ 90 GPH to feed even the hungriest motor. Sierra 10 micron filters are recommended to prevent damage to sensitive inboard and outboard fuel injection systems.

| Sierra # | Honda # | Description |
|----------|-----------------|----------------------------|
| 18-7947 | 17670-ZW1-030GH | Spin on Replacement Filter |
| 18-7948 | 17670-ZW1-801AH | Spin on Replacement Filter |
| 18-7720 | 16900-SR3-004 | Fuel Filter |
| 18-7786 | 16900-SA5-004 | Fuel Filter Kit |
| 18-7785 | 16010-ST5-993 | Fuel Filter Kit |

9' LENGTH COMPLETE FUEL LINE ASSEMBLIES



3/8"
FUEL LINE ASSEMBLY

18-81042EP-2 *SILVERADO 4000 Premium*

OE# 17700-ZW9-010
17700-ZW9-020



*



18-80400
TANK
CONNECTOR
(SOLD SEPARATELY)



18-80401
FUEL
CONNECTOR



18-8005EP-1
PRIMER
BULB



18-80403
FUEL
CONNECTOR

*

FUEL LINE ASSEMBLY COMPONENTS

Honda Fuel Application: 8, 9.9, 15, 25, 30, 40, 50, 75, 90, 115, 130 HP (2001-02)

* Tanks and Engines for picture purpose only.



18-8002EP-1
18-8002EP-1-10①
PRIMER BULB
1/4"

18-8004EP-1
18-8004EP-1-10①
PRIMER BULB
5/16"
Large capacity bulb

18-8005EP-1
18-8005EP-1-10①
PRIMER BULB
3/8"
Replaces: 174512
Large capacity bulb



18-38008
FUEL CONNECTOR
Replaces: 17660-ZV5-902
Fits: 3/8" hose barb, Use with 18-80406



18-80401
FUEL CONNECTOR
Female hose connector, new style, 3/8" hose. Will not interchange with OE's 5/16" hose assemblies.
Mates with 18-80400, tank outlet



18-80403
FUEL CONNECTOR
Female 3/8 hose connector with rectangular locking post. Will not interchange with OE's 5/16" hose assemblies. For late model engine: For use with our 18-81042 fuel hose assembly, motor end.
Mates with 18-80407



18-80400
TANK CONNECTOR
Replaces: 16977-ZV5-A00
Male tank outlet, new style, 1/4"NPT, nickel plated brass. Male connector, for fuel tank.
Mates with 18-80401



18-80406
FUEL CONNECTOR
Replaces: 16977-ZV5-900
Male tank outlet, old style, 1/4" NPT.



18-80407
FUEL CONNECTOR
Replaces: 17710-ZW9-033
5/16" with interlocking post
Fits: BF8-BF130 (2003)
Mates with 18-80403, 18-80408



18-80408
FUEL CONNECTOR
Replaces: 17650-ZW9-003
Female 5/16" connector with rectangular locking post. Fits late model engine
Mates with 18-80407



18-80420
FUEL CONNECTOR
Replaces: 17650-921-003ZB
Fits: BF5/BF8A 2001 and earlier
Mates with 17710-881-00ZA

FUEL FILTERS



| Part No. | OE No. |
|-----------|---------------|
| 18-7712 | 16910-GB2-005 |
| 18-8226 * | 16910-ZV4-015 |

* Retail Packaged Item



18-79908
FUEL FILTER
Replaces: 16911-ZY3-010
Fits: BF90(2007 & Up), BF115(1997 & Below, 2002 & Up), BF130(2002-04), BF135(2004 & Up), BF150(2004 & Up), BF175(2007 & Up), BF200(2002 & Up), BF225(2002 & Up), BF250(1997 & Below)




18-79909
FUEL FILTER
Replaces: 16901-ZY3-003
Fits: BF115D LA, BF115D XA, BF115D XCA, BF115DK1 LA, BF115DK1 XA, BF115DK1 XCA, BF135A4 LA, BF135A4 XA, BF135A4 XCA, BF135A5 LA, BF135A5 XA, BF135A5 XCA, BF135A6 LA, BF135A6 XA, BF135A6 XCA, BF135AK0 LA, BF135AK0 XA, BF135AK0 XCA, BF135AK2 LA, BF135AK2 XA, BF135AK2 XCA, BF150A4 LA, BF150 4 XA, BF150A4 XCA, BF150A5 LA, BF150A5 XA, BF150A5 XCA, BF150A6 LA, BF150A6 XA, BF150A6 XCA, BF150AK0 LA, BF150AK0 XA, BF150AK0 XCA, BF175AK1 LA, BF175AK1 XA, BF175AK1 XCA, BF175AK2 LA, BF175AK2 XA, BF175AK2 XCA, BF200A2 LA, BF200A2 XA, BF200A2 XCA, BF200A2 XXA, BF200A2 XXCA, BF200A3 LA, BF200A3 XA, BF200A3 XCA, BF200A3 XXA, BF200A3 XXCA, BF200A4 LA, BF200A4 XA, BF200A4 XCA, BF200A4 XXA, BF200A4 XXCA, BF200A5 LA, BF200A5 XA, BF200A5 XCA, BF200A5 XXA, BF200A6 LA, BF200A6 XA, BF200A6 XCA, BF200A6 XXA, BF200AK0 LA, BF200AK0 XA, BF200AK0 XCA, BF200AK1 LA, BF200 AK1 XA, BF200AK1 XCA, BF200AK2 LA, BF200AK2 XA, BF200AK2 XCA



18-7599
FUEL LOCK
Protect your outboard from theft, disconnect fuel line and simply install fuel lock. Designed to fit clip on style fuel connectors. Fits: Johnson Evinrude, Mercury/Mariner, Yamaha and Honda.

| | | | |
|---|---|--|--|
|  <p>18-7657 OXYGEN SENSOR Replaces: 35655-ZY3-013</p> |  <p>18-7658 OXYGEN SENSOR Replaces: 35655-ZY9-003</p> |  <p>18-7659 OXYGEN SENSOR Replaces: 35668-ZY6-003</p> |  <p>18-32153 OXYGEN SENSOR Replaces: 35655-ZY3-C01, 35655-ZZ5-004 Fits: BF40D, BF50D, BF250A (1997 & Prior), BF40DK2, BF50DK2, BF225AK1, BF225AK2 (2007 & Up)</p> |
|  <p>18-25200 CAMSHAFT SENSOR Replaces: 37500-PNB-003 Fits: 75 hp MF1</p> |  <p>18-25201 CAMSHAFT SENSOR Replaces: 37510-PNB-003 Fits: BF5 (2007 & Up), BF135 (2004 & Up), BF150 (2004 & Up)</p> |  <p>18-7552 SENSOR, MAP Replaces: 37830-PGK-A01 Fits: BF135A 2004-2006, BF135AK0, BF150A 2004-2006, BF150AK0, BF200A 2002-2006, BF200AK0, BF225A 2002-2006, BF225AK0</p> |  <p>18-7558 SENSOR, KNOCK Replaces: 30530-PPL-A01 Fits: BF135A 2004-2006, BF150 2004-2006</p> |
|  <p>18-7559 SENSOR, KNOCK Replaces: 30530-P8F-A01 Fits: BF200A 2002-2006, BF200AK0, BF225 2002-2006, BF225AK0</p> |  <p>18-7050 CARB KIT Fits: BF9.9(2000 & below), BF15(2002 & below)</p> |  <p>18-7051 CARB KIT Fits: BF9.9(2001 & Up), BF15(2003 & Up)</p> |  <p>18-7052 CARB KIT Fits: BF75(1997 & Up), BF90(1997 & Up)</p> |
|  <p>18-7053 CARB KIT Fits: BF8(1996 & below)BF75(1996 & below), BF100(1996 & below)</p> |  <p>18-7047 NEEDLE VALVE Replaces: 16011-ZV4-005 Fits: BF8(2001 & Up), BF9.9(All), BF15(All), BF20(2003 & Up), BF25(All), BF30(All), BF35(1997), BF40(All), BF45(1997), BF50(All), BF75(1997 & Up), BF90(1997 & Up)</p> |  <p>18-7048 NEEDLE VALVE Replaces: 16011-881-741 Fits: BF5(2003 & below), BF8(All), BF75(1997 & below), BF100(1997 & below)</p> | |
|  <p>18-3627 THERMOSTAT Replaces: 19300-881-761 For: BF5A1, BF5A2, BF5A3, BF5A4, BF5A5, BF5A6, BF5AH, BF5AK, BF5AK0, BF5AM, BF5AW, BF5AX, BF5AY, BF8A3, BF8A4, BF8A5, BF8A6, BF8AH, BF8AK, BF8AK0, BF8AM, BF8AW, BF8AX, BF8AY, BF9.9AH, BF9.9AK, BF9.9AM, BF9.9AW, BF9.9AX, BF9.9AY, BF15A1, BF15A2, BF15AH, BF15AK, BF15AM, BF15AW, BF15AX, BF15AY, BF50F, BF75E, BF75F, BF100E, BF100F 52°C</p> |  <p>18-3628-1 THERMOSTAT Replaces: 19300-ZW9-003 For: BF8D1, BF8D2, BF8D3BF15D3, BF15D4, BF15D5, BF15D6, BF15DK0, BF20D3, BF20D4, BF20D5, BF20D6, BF20DK0, BF25D4, BF25D5, BF25D6, BF25DK0, BF30D4, BF30D5, BF30D6, BF30DK0, BF40A4, BF40A5, BF40A6, BF40AK0, BF40D, BF50A4, BF50A5, BF50A6, BF50AK0, BF50D, BF60A, BFP60A, BF75DK0, BF90DK0, BF200A2, BF225A2 60°C</p> |  <p>18-3629 THERMOSTAT Replaces: 19300-881-741, 19300-921-003 For: BF8AM, BF8AW, BF8AX, BF8AY, BF8A3, BF8A4, BF8A5, BF8A6, BF8AK, BF75, BF75A, BF75B, BF75C, BF75D, BF75E, BF75F, BF75K1, BF75K2, BF75K3, BF75Z, BF100, BF100A, BF100B, BF100C, BF100D, BF100E, BF100F, BF100Z 62°C</p> | |

① Discount shop pack of 10 - Priced per package



18-3630
THERMOSTAT

Replaces: 19300-ZV5-043
For: BF25A, BF25A1, BF25A2, BF25A3, BF25AW, BF25AX, BF25AY, BF30A, BF30A1, BF30A2, BF30A3, BF30AW, BF30AX, BF30AY, BF35AM, BF40A, BF40A1, BF40A2, BF40A3, BF40AW, BF40AX, BF40AY, BF45AM, BF50A, BF50A1, BF50A2, BF50A3, BF50AW, BF50AX, BF50AY, BF75A1, BF75A2, BF75A3, BF75A4, BF75A6, BF75AT, BF75AW, BF75AX, BF75AY, BF90A1, BF115A1, BF115A2, BF115AX, BF115AY, BF130A1, BF130A2, BF130AX, BF130AY
72°C



18-3031
IMPELLER

Replaces: 19210-ZY3-003
Fits: BF200 & BF225 (2002 & Up)



18-3100
IMPELLER

Replaces: 19210-ZW9-013, 19210-ZW9-003
Fits: BF8D/9.9D short, long shaft



18-3056
18-3056-10②
IMPELLER

Replaces: 19210-ZW1-003
For: 75-90 HP



18-3245
IMPELLER

Replaces: 19210-881-A01, 19210-881-A02, 19210-ZW9-A02
For: 5, 7.5, 8, 10 HP



18-32455
IMPELLER

Replaces: 19210-ZW9-A32, 19210-ZW9-A31
For: Honda 8 & 9.9 (2001 & Up); Honda 15 & 20 (2003 & Up)



18-3246
IMPELLER

Replaces: 19210-ZV4-013, 19210-ZV4-651
For: BF9.9, BF15, AH, AK, AM, AW Series # 14ZV40M



18-3247
IMPELLER

Replaces: 19210-ZV4-651
For: 8, 9.9, 15 HP



18-3248
IMPELLER

Replaces: 19210-ZV5-003
For: 35, 40, 45, 50 HP



18-3249
IMPELLER

Replaces: 19210-ZV7-003
For: 25, 30 HP



18-3250
IMPELLER

Replaces: 19210-ZW1-B04
For: 75, 90, 115, 130 HP



18-3122
IMPELLER PLATE

Replaces: 19231-ZW1-003
For: 75-90 HP



18-3268
IMPELLER KEY

Replaces: 90752-ZV4-650
Fits: BF9.9A, BF15A




18-3269
IMPELLER KEY

Replaces: 90752-ZV7-000
Fits: BF25, BF30



18-3270
IMPELLER KEY

Replaces: 90752-ZV5-003
Fits: BF35, BF40, BF45, BF50



18-3271
IMPELLER KEY

Replaces: 90752-ZW1-B02
Fits: BF75-BF90 AX & Up, BF115, BF130



18-3273
IMPELLER KEY

Replaces: 90752-ZY3-003
Fits: BF200, BF225



18-3187
IMPELLER REPAIR KIT

Replaces: 06192-ZW1-305
Fits: BF75-90, (1996-98)
Includes impeller 18-3056



① **18-3214D**

18-3214
WATER PUMP KIT

Replaces: 19021-ZW1-003
For: BF 70/BF 90 1996-98
Includes impeller 18-3056






18-3278
WATER PUMP SERVICE KIT
Replaces: 06192-ZV1-C00
Fits: BF5
Includes impeller **18-3245**




18-3279
WATER PUMP SERVICE KIT
Replaces: 06192-881-C00
Fits: BF8A (USA)
Includes impeller **18-3245**




18-3280
WATER PUMP SERVICE KIT
Replaces: 06192-ZV4-000
Fits: BF9.9A/BF15A
Includes impeller **18-3247**




18-3281
WATER PUMP SERVICE KIT
Replaces: 06192-ZV7-000
Fits: BF25/30
Includes impeller **18-3249**




18-3282
WATER PUMP SERVICE KIT
Replaces: 06192-ZV5-003
Fits: BF35/45, BF40/50
Includes impeller **18-3248**




18-3283
WATER PUMP SERVICE KIT
Replaces: 06192-ZW1-000
Fits: BF115/130, BF75/90 AX & Later
Includes impeller **18-3250**



18-3284
WATER PUMP SERVICE KIT
Replaces: 06192-ZY6-000
Fits: BF135 / BF150
Includes impeller **18-3250**




18-3285
WATER PUMP SERVICE KIT
Replaces: 06192-ZY3-000
Fits: BF200/225
Includes impeller **18-3031**




18-3478
WATER PUMP REPAIR KIT
Without Housing
Replaces: 06192-ZW9-A30
Fits: BFP8D/BFP9.9D (2003-06), BF15D/BF20D (2003-06), BFP20D (2004-06), BFP8D/BFP9.9D/BF15D/BFP15D/BF20D (K0, K2, K3), BFP20D (K0)

| Part # | Desc. | O.E.# | Qty. |
|----------|--------------------|---------------|------|
| 18-32455 | Impeller | 19210-ZW9-A32 | 1 |
| 18-99153 | Gasket, Water Pump | 19232-ZW9-000 | 1 |
| 18-71335 | O-Ring | 91301-ZG3-000 | 1 |
| 18-3025 | Key, Impeller | 90752-ZW9-A30 | 1 |



18-3489
WATER PUMP REPAIR KIT
Without Housing
Replaces: 06192-ZX2-C00
Fits: BF250A (ALL)

| Part # | Desc. | O.E.# | Qty. |
|----------|--------------------|---------------|------|
| 18-3031 | Impeller | 19210-ZY3-003 | 1 |
| 18-99154 | Gasket, Water Pump | 19234-ZX2-C00 | 1 |
| 18-8299 | O-Ring | 91356-ZY3-003 | 1 |
| 18-3273 | Key, Impeller | 90752-ZY3-003 | 1 |




18-3492
WATER PUMP REPAIR KIT
Without Housing
Replaces: 06192-ZW1-B03
Fits: BF75A/BF90A/BF115A/BF130A (1999-02)

| Part # | Desc. | O.E.# | Qty. |
|---------|--------------------|---------------|------|
| 18-3250 | Impeller | 19210-ZW1-B04 | 1 |
| 18-0481 | Gasket, Water Pump | 19234-ZW1-B00 | 1 |
| 18-0482 | Gasket, Water Pump | 19242-ZW1-B00 | 1 |
| 18-1820 | Seal, Water Pump | 91251-ZW1-B04 | 2 |



18-3493
WATER PUMP REPAIR KIT
Without Housing
Replaces: 06192-ZW9-000
Fits: BF8D/BFP8D/BF9.9D/BFP9.9D (2002-06), BF8D, BFP8D/BF9.9D/BFP9.9D (K0, K2, K3)

| Part # | Desc. | O.E.# | Qty. |
|----------|--------------------|---------------|------|
| 18-3100 | Impeller | 19210-ZW9-013 | 1 |
| 18-99153 | Gasket, Water Pump | 19232-ZW9-000 | 1 |
| 18-71335 | O-Ring | 91301-ZG3-000 | 1 |
| 18-3022 | Key, Impeller | 90752-ZW9-000 | 1 |



18-4536
WATER PUMP REPAIR KIT
Without Housing
Replaces: 06192-ZV4-A00
Fits: BF9.9A/15A (1998-01)

| Part # | Desc. | O.E.# | Qty. |
|---------|--------------------|---------------|------|
| 18-3247 | Impeller | 19210-ZV4-651 | 1 |
| 18-2495 | Gasket, Water Pump | 19232-ZV4-610 | 2 |
| 18-8298 | Seal, Water Pump | 91252-935-004 | 1 |

① Items ending in "D" are Display Packaged - Regular number is Non-Display • ② Discount shop pack of 10 - Priced per package

HONDA 4-STROKE WATER PUMP REPAIR KIT APPLICATION

| Model | HP | Year | Honda Code | Impeller | Gasket | Kit without Housing |
|---------|-----|------------|------------|----------|--------------------|---------------------|
| BF5A | 5 | 1998-06 | 6315899 | 18-3245 | 18-2524 | 18-3278 |
| BF5A | 5 | K0, K2, K3 | 6315899 | 18-3245 | 18-2524 | 18-3278 |
| BF8A | 8 | 1998-00 | 6315386 | 18-3245 | 18-2608 18-2609 | 18-3279 |
| BF8A | 8 | 2003-06 | 6315386 | 18-3245 | 18-2608 18-2609 | 18-3279 |
| BF8A | 8 | K0 | 6315386 | 18-3245 | 18-2608 18-2609 | 18-3279 |
| BF8D | 8 | 2002-06 | 7452345 | 18-3100 | 18-99153 | 18-3493 |
| BF8D | 8 | K0, K2, K3 | 7452345 | 18-3100 | 18-99153 | 18-3493 |
| BFP8D | 8 | 2002-06 | 7452345 | 18-3100 | 18-99153 | 18-3493 |
| BFP8D | 8 | 2002-06 | 7452352 | 18-32455 | 18-99153 | 18-3478 |
| BFP8D | 8 | K0, K2, K3 | 7452345 | 18-3100 | 18-99153 | 18-3493 |
| BFP8D | 8 | K0, K2, K3 | 7452352 | 18-32455 | 18-99153 | 18-3478 |
| BF9.9A | 9.9 | 1998-01 | 6310494 | 18-3247 | 18-2495 | 18-4536 |
| BF9.9A | 9.9 | 1999-02 | 7452360 | 18-3247 | 18-2495 | 18-3280 |
| BF9.9D | 9.9 | 2002-06 | 7452345 | 18-3100 | 18-99153 | 18-3493 |
| BF9.9D | 9.9 | K0, K2, K3 | 7452345 | 18-3100 | 18-99153 | 18-3493 |
| BFP9.9D | 9.9 | 2002-06 | 7452345 | 18-3100 | 18-99153 | 18-3493 |
| BFP9.9D | 9.9 | 2002-06 | 7452352 | 18-32455 | 18-99153 | 18-3478 |
| BFP9.9D | 9.9 | K0, K2, K3 | 7452345 | 18-3100 | 18-99153 | 18-3493 |
| BFP9.9D | 9.9 | K0, K2, K3 | 7452352 | 18-32455 | 18-99153 | 18-3478 |
| BF15A | 15 | 1998-01 | 6310494 | 18-3247 | 18-2495 | 18-4536 |
| BF15A | 15 | 1999-02 | 7452360 | 18-3247 | 18-2495 | 18-3280 |
| BF15D | 15 | 2003-06 | 7452352 | 18-32455 | 18-99153 | 18-3478 |
| BF15D | 15 | K0, K2, K3 | 7452352 | 18-32455 | 18-99153 | 18-3478 |
| BFP15D | 15 | K0, K2, K3 | 7452352 | 18-32455 | 18-99153 | 18-3478 |
| BF20D | 20 | 2003-06 | 7452352 | 18-32455 | 18-99153 | 18-3478 |
| BF20D | 20 | K0, K2, K3 | 7452352 | 18-32455 | 18-99153 | 18-3478 |
| BFP20D | 20 | 2004-06 | 7452352 | 18-32455 | 18-99153 | 18-3478 |
| BFP20D | 20 | K0 | 7452352 | 18-32455 | 18-99153 | 18-3478 |
| BF25A | 25 | 2001-03 | 7452378 | 18-3249 | 18-2496 | 18-3281 |
| BF25D | 25 | 2004-06 | 7452378 | 18-3249 | 18-2496 | 18-3281 |
| BF25D | 25 | K0, K2, K3 | 7452378 | 18-3249 | 18-2496 | 18-3281 |
| BF30A | 30 | 2001-03 | 7452378 | 18-3249 | 18-2496 | 18-3281 |
| BF30D | 30 | 2004-06 | 7452378 | 18-3249 | 18-2496 | 18-3281 |
| BF30D | 30 | K0, K2, K3 | 7452378 | 18-3249 | 18-2496 | 18-3281 |
| BF40A | 40 | 2000-06 | 7452386 | 18-3248 | 18-2496 18-0176 | 18-3282 |
| BF40A | 40 | K0 | 7452386 | 18-3248 | 18-2496 18-0176 | 18-3282 |
| BF40D | 40 | K2 | 7452386 | 18-3248 | 18-2496 18-0176 | 18-3282 |
| BF40D | 40 | Pre-1997 | 7452386 | 18-3248 | 18-2496 18-0176 | 18-3282 |
| BF50A | 50 | 2000-06 | 7452386 | 18-3248 | 18-2496 18-0176 | 18-3282 |
| BF50A | 50 | K0 | 7452386 | 18-3248 | 18-2496 18-0176 | 18-3282 |
| BF50D | 50 | K2 | 7452386 | 18-3248 | 18-2496 18-0176 | 18-3282 |
| BF50D | 50 | Pre-1997 | 7452386 | 18-3248 | 18-2496 18-0176 | 18-3282 |
| BF75A | 75 | 1997-98 | 4921441 | 18-3056 | 18-2565 | 18-3214 |
| BF75A | 75 | 1999-02 | 6706634 | - | - | 18-3492 |
| BF75A | 75 | 2003-06 | 7452394 | 18-3250 | NSS | 18-3283 |
| BF75D | 75 | K0, K2 | 7452394 | 18-3250 | NSS | 18-3283 |
| BF90A | 90 | 1997-98 | 4921441 | 18-3056 | 18-2565 | 18-3214 |

APPLICATION CONTINUED ON NEXT PAGE

HONDA 4-STROKE WATER PUMP REPAIR KIT APPLICATION (CONT.)

| Model | HP | Year | Honda Code | Impeller | Gasket | Kit without Housing |
|--------|-----|------------|------------|----------|--------------------|---------------------|
| BF90A | 90 | 1999-02 | 6706634 | - | - | 18-3492 |
| BF90A | 90 | 2003-06 | 7452394 | 18-3250 | NSS | 18-3283 |
| BF90D | 90 | K0, K2 | 7452394 | 18-3250 | NSS | 18-3283 |
| BF115A | 115 | 1999-02 | 6706634 | - | - | 18-3492 |
| BF115A | 115 | 2003-06 | 7452394 | 18-3250 | NSS | 18-3283 |
| BF115A | 115 | K0 | 7452394 | 18-3250 | NSS | 18-3283 |
| BF115D | 115 | K1 | 7632797 | 18-3250 | 18-2497 | 18-3284 |
| BF115D | 115 | Pre-1997 | 7632797 | 18-3250 | 18-2497 | 18-3284 |
| BF130A | 130 | 1999-02 | 6706634 | - | - | 18-3492 |
| BF130A | 130 | 2003-04 | 7452394 | 18-3250 | NSS | 18-3283 |
| BF135A | 135 | 2004-06 | 7632797 | 18-3250 | 18-2497 | 18-3284 |
| BF135A | 135 | K0, K2 | 7632797 | 18-3250 | 18-2497 | 18-3284 |
| BF150A | 150 | 2004-06 | 7632797 | 18-3250 | 18-2497 | 18-3284 |
| BF150A | 150 | K0, K2 | 7632797 | 18-3250 | 18-2497 | 18-3284 |
| BF175A | 175 | K1 | 7452402 | 18-3031 | 18-2499 18-8299 | 18-3285 |
| B175A | 175 | K2 | 7452402 | 18-3031 | 18-2499 18-8299 | 18-3285 |
| BF200A | 200 | 2002-06 | 7452402 | 18-3031 | 18-2499 18-8299 | 18-3285 |
| BF200A | 200 | K0, K1, K2 | 7452402 | 18-3031 | 18-2499 18-8299 | 18-3285 |
| BF225A | 225 | 2002-06 | 7452402 | 18-3031 | 18-2499 18-8299 | 18-3285 |
| BF225A | 225 | K0, K1, K2 | 7452402 | 18-3031 | 18-2499 18-8299 | 18-3285 |
| BF250A | 250 | ALL | | 18-3031 | 18-99154 | 18-3489 |

| | | | |
|--|--|---|--|
|  <p>18-2499 WATER PUMP GASKET Replaces: 19234-ZY3-000 Fits: BF200, BF225</p> |  <p>18-2524 WATER PUMP GASKET Replaces: 19232-ZV1-A10 Fits: BF5</p> |  <p>18-2608 WATER PUMP GASKET Replaces: 19232-881-850 Fits: BF8A</p> |  <p>18-2609 WATER PUMP GASKET Replaces: 19234-881-850 Fits: BF8A</p> |
|  <p>18-0176 WATER PUMP GASKET Replaces: 19242-ZV5-000</p> |  <p>18-2495 WATER PUMP GASKET Replaces: 19232-ZV4-610 Fits: BF9.9A, BF15A</p> |  <p>18-2496 WATER PUMP GASKET Replaces: 19233-ZV5-000 Fits: BF25, BF30</p> | <p>PKG. OF 2</p>  <p>18-2563 18-2563-9 ① IMPELLER GASKET Replaces: 19232-ZW1-003</p> |
| <p>PKG. OF 2</p>  <p>18-2564 18-2564-9 ① IMPELLER GASKET Replaces: 19234-ZW1-003</p> | <p>PKG. OF 2</p>  <p>18-2565 18-2565-9 ① IMPELLER GASKET Replaces: 19242-ZW1-003</p> |  <p>18-2480 GASKET SET Replaces: 16010-ZV4-005 Fits: BF8(2001), BF9.9(2001 & below), BF15(2002 & below), BF25(All), BF30(All), BF35(1997), BF40(All), BF45(1997), BF50(All), BF75(1997-06), BF90(1997-06)</p> |  <p>18-2481 GASKET SET Replaces: 16010-ZW9-003 Fits: BF8(2002 & Up), BF9.9(2002 & Up), BF15(2003 & Up), BF20(2003 & Up)</p> |


SEE PAGES 201-202 FOR OUR COMPLETE LINE OF GASKET SEALANTS

① Priced Per Package




18-2482
GASKET SET

Replaces: 16010-881-003
Fits: BF5(2003 & below), BF8(2000 & below, 2003 & Up), BF50(1996 & below), BF75(1996 & below), BF100(1996 & below)



18-2470
CARB MOUNTING GASKET

Replaces: 16221-ZV4-610
Fits: BF9.9 (2000 & below), BF15 (2002 & below)




18-2471
CARB MOUNTING GASKET

Replaces: 16221-ZW9-000
BF8(2001 & Up), BF9.9(2001 & Up)



18-2472
CARB MOUNTING GASKET

Replaces: 16221-ZW1-000
Fits: BF75(1997-06), BF90(1997-06)



18-2473
CARB MOUNTING GASKET

Replaces: 16201-881-850
Fits: BF8(2000 & below, 2003 & Up), BF75(1996 & below), BF100(1996 & below)

PKG. OF 2




18-2945
18-2945-9①
18-29451-9①
(PKG. OF 50)
DRAIN SCREW GASKET
Used with **18-2244** Drain Screw



18-0300
INTAKE MANIFOLD GASKET

Replaces: 17105-ZY6-000
Fits: BF135-BF150



18-0390
INTAKE MANIFOLD GASKET

Replaces: 17105-ZY3-004
Fits: BF200-BF225 (2002 and UP)



18-0248
INTAKE MANIFOLD GASKET
Replaces: 17151-ZW5-000




18-0382
THROTTLE BODY GASKET

Replaces: 17109-ZY6-000
Fits: BF75-BF150



18-0396
THROTTLE BODY GASKET

Replaces: 17109-ZY3-004
Fits: BF200-BF225 (2002 & UP)



18-0737
THROTTLE BODY GASKET
Replaces: 16176-P0A-004




18-3288
SEAL

Replaces: 91252-ZV1-003
Fits: BF5



18-8298
SEAL

Replaces: 91252-935-004
Fits: BF8A



18-8299
MOLDED RUBBER SEAL (O-RING MATERIAL)

Replaces: 91356-ZY3-003
Fits: BF200, BF225

SEE PAGES 201-202 FOR OUR COMPLETE LINE OF GASKET SEALANTS

① Priced per Package

| | | |
|---|---|--|
|  <p>18-1156 FORWARD GEAR BEARING Replaces: 91051-ZW1-003</p> |  <p>18-1157 FORWARD GEAR INNER BEARING Replaces: 91057-ZW1-003</p> |  <p>18-1158 CARRIER BEARING Replaces: 91053-ZW1-003</p> |
|  <p>18-7909 OIL FILTER Replaces: 15400-POH-305PE, 15400-POH-305, 15400-ZJ1-004, 15400-PLM-A01PE (Application on next page)</p> |  <p>18-7913 OIL FILTER Replaces: 15400-PFB-014 (Application on next page)</p> |  <p>18-7911-1 OIL FILTER Replaces: 15400-PFB-007 (Application on next page)</p> |

| Models | Years | SS Number | Replace | Part No. | Models | Years | SS Number | Replace | Part No. |
|---------------|--------------|---------------|---------------|----------------|--------------|--------------|-----------------|-----------------|------------------|
| BF8D, BFP8D | 2001-Current | 15400-PFB-004 | 15400-PFB-014 | 18-7913 | BF50A | 1998-Earlier | 15400-PJ7-005 | 15400-PFB-014 | 18-7913 |
| BF9D, BFP9D | 2001-Current | 15400-PM3-004 | 15400-PFB-014 | 18-7913 | BF25 | 1999-2005 | 15400-ZW4-003 | 15400-PFB-007 | 18-7911-1 |
| BF15D, BFP15D | 2003-Current | 15400-PM3-405 | 15400-PFB-014 | 18-7913 | BF30 | 1999-2005 | 15400-ZW4-003 | 15400-PFB-007 | 18-7911-1 |
| BF20D | 2003-Current | 15400-PJ7-015 | 15400-PFB-014 | 18-7913 | BF40 | 1999-2005 | 15400-ZW4-003 | 15400-PFB-007 | 18-7911-1 |
| BF25A | 1998-Earlier | 15400-PJ7-005 | 15400-PFB-014 | 18-7913 | BF50 | 1999-2005 | 15400-ZW4-003 | 15400-PFB-007 | 18-7911-1 |
| BF30A | 1998-Earlier | 15400-PJ7-005 | 15400-PFB-014 | 18-7913 | BF75, BF90 | 1997-Current | 15400-POH-305PE | 15400-PLM-A01PE | 18-7909 |
| BF35AM | 1998-Earlier | 15400-PJ7-005 | 15400-PFB-014 | 18-7913 | BF115, BF130 | 1999-Current | 15400-POH-305 | 15400-PLM-A01PE | 18-7909 |
| BF40A | 1998-Earlier | 15400-PJ7-005 | 15400-PFB-014 | 18-7913 | BF135, BF150 | 2004-Current | 15400-ZJ1-004 | 15400-PLM-A01PE | 18-7909 |
| BF45AM | 1998-Earlier | 15400-PJ7-005 | 15400-PFB-014 | 18-7913 | BF200, BF225 | 2002-Current | 15400-ZJ1-999AH | 15400-PLM-A01PE | 18-7909 |

Zinc is for saltwater only applications.
Magnesium is for fresh water only applications.
Aluminum is for brackish water, or if boat is used in both fresh and salt environments.

| | |
|---|--|
|  <p>18-2448 LOWER UNIT FILL/DRAIN KIT • M8 - 1.25 thread Fits: Yamaha, Nissan/Tohatsu, & Honda Lower Units</p> |  <p>③ 18-6068 ANODE Replaces: 41109-ZW1-003 BF75-BF90 (1997-98)</p> |
|---|--|

SEE PAGES 182-184 & 1147-1170 FOR ADDITIONAL OIL FILTER INFORMATION

- ① Aluminum ② Magnesium ③ Zinc ④ Priced per Package
- ⑤ Items ending in "D" are Display Packaged - Regular number is Non-Display



② 18-6241
 ③ 18-6011
 ① 18-6011A
ANODE
 Replaces: 41107-ZW1-003ZA
 BF75-BF90 (1997-98)



① 18-6165A
ANODE, TRIM TAB
 Replaces: 41107-ZV5-00-00
 Fits: BF25, BF30, BF35, BF45, BF50 (1997-Up)



① 18-6163A
 ② 18-6163M
ANODE KIT
 Fits: Honda BF90-115 Engines

PKG. OF 10



18-3200
 18-3200-9④
TAB WASHER
 Replaces: 90508-ZW1-003
 For: 75-90 HP

⑤ 18-3701D




18-3701
PROP NUT KIT
 — CONTAINS —

| Part # | O.E. # | Description |
|---------|---------------|-------------|
| 18-3200 | 90508-ZW1-003 | Tab Washer |
| 18-3700 | 90301-ZW1-003 | Prop Nut |




18-79989
TRAILERING STICKS
 Fits: Most outboards over 150hp with three ram intrigel tilt/trim.




18-8362-1
LOWER UNIT SEAL KIT
 For: Series 14ZV50M



18-8363
LOWER UNIT SEAL KIT



18-8365
LOWER UNIT SEAL KIT



18-8366
LOWER UNIT SEAL KIT



OIL SEALS

| Part No. | Description | O.E. No. |
|----------|-------------|---------------|
| 18-0522 | Drive Shaft | 91254-ZW1-003 |
| 18-0583 | Drive Shaft | 91251-ZW1-003 |
| 18-2002 | Prop Shaft | 91252-ZW1-003 |
| 18-2053 | Prop Shaft | 91255-ZW1-003 |
| 18-2054 | Shift Shaft | 91253-ZW1-003 |

PKG. OF 5



18-7198
 18-7198-9④
O-RING
 Replaces: 91353-ZW1-003

LOWER UNIT SEAL KIT APPLICATION

| HP/Model | Part # |
|--|-----------|
| BF9.9, BF15 | 18-8363 |
| BF35AM, BF45AM, BF40A, BF40AW, BF40AX, BF50A, BF50AW, BF50AX | 18-8362-1 |
| BF75, BF90 | 18-8366 |
| BF115, BF130 | 18-8365 |